Tips & Technology

For Bosch business partners

Current topics for successful workshops No. 10/2010

All modules



Bosch engine control units

Information on the repair service

Nowadays nearly all motor vehicles are equipped with an electric engine control unit. In the event of a fault, replacement with a new part often seems inappropriate particularly with older vehicles.



With the Bosch repair service, the quick, reliable and "present value" repair of gasoline and diesel engine control units is possible. At present this service is only available for Bosch engine control units.

Scope:

- Cleaning of the engine control unit
- Diagnosis and fault analysis
- Fault rectification and replacement of all defective components
- Final inspection
- 12 months warranty

The procedure could not be simpler:

- 1. Enquiry through internet/wholesaler as to whether the repair service is available for the control unit
- 2. Placing of order for repair work via the wholesaler
- 3. On-the-spot collection of the defective control unit in the workshop
- 4. Diagnosis, repair and functional testing at Bosch within 48 hours at most
- 5. Return of the repaired control unit to the workshop. Direct billing of the workshop by the wholesaler.

Inexpensive, fast and reliable

What that means to you: A Bosch quality repair is considerably less expensive than replacement with a new unit. There is a guaranteed fixed price from the start for all repair work.

The fixed price for engine control unit diagnosis is included in the overall price. A separate charge is only made for diagnosis if trouble-shooting has not revealed any faults or the fault cannot be rectified, for example on account of external influences.

What's more: During the repair work, all vehicle-specific settings and peripheral values are retained. The control unit is tailored to the vehicle concerned. In other words: There is no need for tedious, time-consuming matching of immobilizers, injection pumps and entertainment electronics for example.



Just ask your wholesaler!

Further information on the topic of engine control unit repairs can be found under www.werkstattportal.bosch.de.

This information does not claim to be exhaustive. Always make use of the corresponding service documentation when performing testing and repair work. No liability. All rights, including patent applications, as well as sole power of disposal and duplication and transfer rights, reserved by Robert Bosch GmbH.